TM05104 Digital Temperature Panel Meter

This is an easy to use simple function
Temperature panel meter.
It can be mounted in an easy access area
to monitor the temperature in a hard to
reach location.

Specification:

Display: 3-1/2 LCD.
Polarity: Automatic;
             (-) for Minus
             No indication for positive polarity
Temperature display range:
             -30°C to 100 °C
Mounting area temperature
(meter working temperature):
             0 °C to 50 °C
Batteries used:
             1 X 1.5V, A8

Diagram:

1, Panel meter
2, Cable
3, Thermocouple

Changing Battery:

1, Turn the battery door at the back of the meter and remove it away from the meter.
2, Remove the old battery.
3, Insert a flash battery of same type and making sure that the proper polarity is followed.
4, Re-cap the battery door.
5, Dispose the old battery properly.