

## **DTM0503 Digital Temperature Panel Meter**

This is an easy to use simple function  
Temperature panel meter.

It can be mounted in an easy access area  
to monitor the temperature in a hard to  
reach location.

### **Specification:**

Polarity: Automatic;  
(-) for Minus  
No indication for positive polarity


Temperature display range:  
-56 °F to 120 °F

Mounting area temperature  
(meter working temperature):  
0 °C to 50 °C

Batteries used:  
1 X 1.5V, AG8

## Diagram:

- 1, Panel meter
- 2, Cable
- 3, Thermocouple



## Changing Battery:

- 1, Turn the battery door at the back of the meter and remove it away from the meter.
- 2, Remove the old battery.
- 3, Insert a flash battery of same type and making sure that the proper polarity is followed.
- 4, Re-cap the battery door.
- 5, Dispose the old battery properly.